

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
DMGXT	Utilities In Goodrich Road In Vicinity Of Building H-10	CLOSE	PNSY-H10	Oct 3, 2008, 5:15 AM	Sep 20, 2017, 1:53 PM	Sep 20, 2017, 1:53 PM	65	PWD MAINE
H8CMV	Youth Center At Clinic End - Light Fixture Cover Needs To Be Resecured	CLOSE	PNSY-H10	Feb 19, 2009, 7:14 AM	May 28, 2015, 3:38 PM	May 28, 2015, 3:38 PM	65	PWD MAINE
K97L2	REPLACE 2 EMERGENCY LIGHT UNITS #'S B02, B03	CAN	PNSY-H10	Jun 9, 2009, 9:48 AM			65	PWD MAINE
TDH7C	Building H-10, Wood Hobby Shop - Provide Rodent Control. Rats Have Been Seen In The Area	CLOSE	PNSY-H10	Jul 7, 2010, 12:46 PM	May 28, 2015, 3:38 PM	May 28, 2015, 3:38 PM	65	PWD MAINE
X9FJP	Building H-10, Wood Hobby Shop - Need To Provide Rodent Removal ASAP!	CLOSE	PNSY-H10	Nov 29, 2010, 12:40 PM	May 28, 2015, 3:38 PM	May 28, 2015, 3:38 PM	65	PWD MAINE
ZWTYG	Building H-10, 1st Floor, Garage - There Is Water Pouring In Through A Light Fixture From The Storage Area Above.	CAN	PNSY-H10	Apr 11, 2011, 12:08 PM			65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
B6NKWC	H10: YOUTH CENTER, REQUEST RODENT CONTROL	CLOSE	PNSY-H10	Mar 20, 2012, 7:49 AM	Mar 29, 2012, 10:03 AM	Jan 4, 2016, 2:51 PM	65	PWD MAINE
B7KL2Y	Building H-10, Clubhouse Area - The Sprinkler System Is Spraying Water Into The Area	CLOSE	PNSY-H10	May 11, 2012, 9:52 AM	Jan 4, 2016, 2:51 PM	Jan 4, 2016, 2:51 PM	65	PWD MAINE
B7LXC2	Building H-10, Clubhouse Area - The Heating System Circ Pump Is Leaking.	CLOSE	PNSY-H10	May 14, 2012, 12:20 PM	Apr 28, 2014, 12:35 PM	Apr 28, 2014, 12:35 PM	65	PWD MAINE
B8H983	Building H-10, Stairway Leading To Parking Lot On H-1 Side - Repair A Broken Cement Step.	CLOSE	PNSY-H10	Jun 29, 2012, 10:51 AM	Apr 28, 2014, 12:37 PM	Apr 28, 2014, 12:37 PM	65	PWD MAINE
B8YXKL	Building H-10, School Age Program, School Liason Office (Former Dental Clinic) -	CAN	PNSY-H10	Jul 27, 2012, 1:00 PM			65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
B9YNKZ	Building H-10- Request To Have The Mechanical Room Unlocked	CLOSE	PNSY-H10	Sep 25, 2012, 1:00 PM	Sep 26, 2012, 8:00 AM	Sep 26, 2012, 3:00 PM	65	PWD MAINE
BB3XP6	Building H-10, SARP - Panel boxes need to be labeled correctly	CLOSE	PNSY-H10	Sep 28, 2012, 9:31 AM	Oct 15, 2013, 6:00 AM	Nov 15, 2013, 3:30 PM	65	PWD MAINE
BBJ42G	PM SEWER LIFT STATION (WEEKLY)	CLOSE	PNSY-H10	Nov 2, 2012, 11:34 AM	Nov 3, 2012, 6:00 AM	Nov 13, 2012, 3:00 AM	65	PWD MAINE
BBJ5HD	Building H-10, Outdoor Recreation Area - Please Provide The Following Locks & Keys:	CAN	PNSY-H10	Nov 2, 2012, 12:48 PM			65	PWD MAINE
BBJPGZ	PM SEWER LIFT STATION (MONTHLY)	CLOSE	PNSY-H10	Nov 5, 2012, 10:10 AM	Nov 5, 2012, 6:00 PM	Nov 20, 2012, 3:00 AM	65	PWD MAINE
BBLJHW	PM SEWER LIFT STATION (WEEKLY)	CLOSE	PNSY-H10	Nov 9, 2012, 12:36 PM	Nov 12, 2012, 6:00 AM	Nov 20, 2012, 3:00 AM	65	PWD MAINE
BDBKN6	Bldg. H-10, relocate electrical service that is in the child play area.	CLOSE	PNSY-H10	Mar 21, 2013, 12:49 PM	Mar 21, 2013, 2:00 PM	Mar 25, 2013, 3:30 PM	65	PWD MAINE
BDKKX8	B-H10_ SARP Area_ Install water cooler	CLOSE	PNSY-H10	Apr 3, 2013, 9:36 AM	Apr 3, 2014, 10:00 AM	Apr 23, 2014, 2:30 PM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
BF2ZLV	Building H-10, Clubhouse (downstairs bldg H-10) -	CLOSE	PNSY-H10	May 8, 2013, 10:43 AM	May 8, 2013, 1:30 PM	May 8, 2013, 3:00 PM	65	PWD MAINE
BRW4Z7	Building H-10, Youth Center, Clubhouse Area In The Back - There Is A Pipe Located By The Windows That Is Leaking	CLOSE	PNSY-H10	May 30, 2013, 1:55 PM	May 31, 2013, 7:00 AM	May 31, 2013, 11:00 AM	65	PWD MAINE
BS3PTJ	Bldg. H-10 Remove/Replace worn hot water pump. Pipefitters	CLOSE	PNSY-H10	Jun 14, 2013, 7:03 AM	Jun 15, 2013, 6:00 AM	Jul 16, 2013, 2:30 PM	65	PWD MAINE
BS76JP	Building H-10, Youth Center - Request Relamping In The Boys Bathroom	CLOSE	PNSY-H10	Jun 21, 2013, 11:01 AM	Jun 21, 2013, 1:29 PM	Jul 16, 2013, 10:24 AM	65	PWD MAINE
BSJPXH	Building H10, Youth Program - The Back Fire Exit Door Keeps Sticking.	CLOSE	PNSY-H10	Jul 8, 2013, 9:02 AM	Jul 8, 2013, 11:53 AM	Jul 8, 2013, 12:08 PM	65	PWD MAINE
BSN9ML	Building H-10 - FIRE ALARM PANEL,	CLOSE	PNSY-H10	Jul 22, 2013, 6:35 AM	Jul 29, 2013, 2:00 PM	Jul 29, 2013, 6:00 PM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
BT34SJ	Building H-10, 2nd Floor, Last Office On The Right, Paulette's Office - Relamp As Needed In Area	CLOSE	PNSY-H10	Aug 7, 2013, 11:46 AM	Aug 8, 2013, 11:25 AM	Aug 19, 2013, 3:16 PM	65	PWD MAINE
BT4Y4H	Building h-10 - Electrical Panels	CLOSE	PNSY-H10	Aug 13, 2013, 12:34 PM	Apr 30, 2014, 3:23 PM	Apr 30, 2014, 3:23 PM	65	PWD MAINE
BTBY3G	Building H-10_First floor Liaison Office_Removal/reist alation of toilet to allow the contractor to install flooring in bathroom area.	CLOSE	PNSY-H10	Aug 26, 2013, 5:11 AM	Aug 26, 2013, 2:00 PM	Aug 28, 2013, 8:00 AM	65	PWD MAINE
BTNFRZ	Building H10, Basement, Outdoor Rec - The Septic Tank Has Overflowed & Septic Waste Is On The Rug	CLOSE	PNSY-H10	Sep 10, 2013, 2:24 PM	Sep 10, 2013, 2:45 PM	Sep 11, 2013, 3:30 PM	65	PWD MAINE
BTNFS7	Building H10, Basement, Outdoor Rec - The Septic Tank Has Overflowed & Septic Waste Is On The Rug	CLOSE	PNSY-H10	Sep 10, 2013, 2:32 PM	Sep 10, 2013, 2:44 PM	Sep 10, 2013, 4:00 PM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
BTNM7N	Building H-10, Basement, Outdoor Rec Area - There Is An Exhaust Fan That Is Inoperable & The Damper Is Humming & Hot To The Touch	CLOSE	PNSY-H10	Sep 11, 2013, 1:01 PM	Sep 17, 2013, 7:00 AM	Oct 2, 2013, 11:00 AM	65	PWD MAINE
BTR4ZL	Building H-10 - Repair/replace sewage grinder pump	CLOSE	PNSY-H10	Sep 17, 2013, 8:55 AM	Apr 30, 2014, 3:23 PM	Apr 30, 2014, 3:23 PM	65	PWD MAINE
BTXXBT	ANNUAL PM, FIRE ALARM CONTROL PANEL	CLOSE	PNSY-H10	Sep 23, 2013, 6:18 AM	Sep 26, 2013, 8:20 AM	Oct 17, 2013, 11:02 AM	65	PWD MAINE
BVC33T	H10: fence by club house back side of H- 10 has come loose and not safe for the children in that area.	CAN	PNSY-H10	Oct 17, 2013, 2:23 PM			65	PWD MAINE
BVFGWB	PM SEWER LIFT STATION (YEARLY)	CLOSE	PNSY-H10	Oct 26, 2013, 8:52 PM	Nov 18, 2013, 6:00 AM	Nov 30, 2013, 4:00 PM	65	PWD MAINE
BVJXPM	Bldg H-10 Basement Storage Area for Day Care	CLOSE	PNSY-H10	Oct 31, 2013, 1:49 PM	Dec 11, 2013, 7:00 AM	Dec 11, 2013, 10:00 AM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
BWC9ND	next to the clinic. the mwr build HEAT it is 60 in the building and going down	CLOSE	PNSY-H10	Dec 9, 2013, 1:59 PM	Dec 10, 2013, 11:00 AM	Dec 10, 2013, 1:30 PM	65	PWD MAINE
BWCLNC	next to the clinic. the mwr build HEAT it is 60 in the building and going down	CLOSE	PNSY-H10	Dec 10, 2013, 7:21 AM	Dec 10, 2013, 9:00 AM	Dec 10, 2013, 11:00 AM	65	PWD MAINE
BWCNBK	CK/REPAIR NO HEAT IN 1ST DECK 'SARP' SHOP AREA	CAN	PNSY-H10	Dec 10, 2013, 10:11 AM			65	PWD MAINE
BWFLDL	Building H-10, Day Care - Per Proposal #222, Fabricate & Install 10 Radiator Covers	CLOSE	PNSY-H10	Dec 17, 2013, 6:47 AM	Jan 20, 2015, 7:59 AM	Jan 20, 2015, 7:59 AM	65	PWD MAINE
BWFWFG	PROVIDE KEY FOR FRONT DOOR	CLOSE	PNSY-H10	Dec 18, 2013, 9:11 AM	Mar 31, 2014, 3:55 PM	Mar 31, 2014, 3:55 PM	65	PWD MAINE
BWH3P9	INVESTIGATE/REPAIR ROOF LEAK AT YOUTH CENTER ENTRANCE....LEAK FROM SNOW BUILDUP	CLOSE	PNSY-H10	Dec 19, 2013, 7:24 AM	Dec 19, 2013, 8:00 AM	Dec 19, 2013, 10:00 AM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
BXBJYK	H10: DEVELOPE ESTIMATE TO REPLACE APPROXIMATELY 20 LF OF 4-INCH SPRINKLER PIPING	CLOSE	PNSY-H10	Feb 4, 2014, 8:25 AM	Apr 4, 2014, 10:08 AM	Apr 4, 2014, 10:08 AM	65	PWD MAINE
BXNLJV	(P) WOOD SHOP AREA OVERHEAD DOOR WILL NOT OPEN. CAN NOT GET MATERIALS AN EUIPMENT OUT.	CLOSE	PNSY-H10	Feb 27, 2014, 2:01 PM	Feb 27, 2014, 2:30 PM	Feb 27, 2014, 3:30 PM	65	PWD MAINE
BXR79G	(E) CLOSET NEXT TO ICE MACHINE HAS A PUTRID SEWER ODOR THAT IS OFFENSIVE TO EMPLOYEES AND CUSTOMERS. THE CRPET AROUND THE DOOR IS ALSO WET.	CLOSE	PNSY-H10	Feb 28, 2014, 7:30 AM	Feb 28, 2014, 9:00 AM	Feb 28, 2014, 3:00 PM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
BXVVFN	Building H10: Replace tile floor, paint walls and repair the door..	CLOSE	PNSY-H10	Mar 12, 2014, 5:16 AM	Dec 18, 2014, 5:54 AM	Dec 18, 2014, 5:54 AM	65	PWD MAINE
BY9JS7	(P) IN THE BASEMENT THE SUMP PUMP IS LEAKING CAUSING DAMAGE REP/REP	CLOSE	PNSY-H10	Mar 25, 2014, 9:11 AM	Mar 25, 2014, 9:30 AM	Mar 25, 2014, 1:30 PM	65	PWD MAINE
BYB3DK	PLUMBING	CLOSE	PNSY-H10	Mar 26, 2014, 5:34 AM	Mar 26, 2014, 9:00 AM	Mar 26, 2014, 11:00 AM	65	PWD MAINE
BYDBSW	QUARTERLY PM ROUTE AIR HANDLING UNIT	CLOSE	PNSY-H10	Apr 2, 2014, 5:29 AM	Apr 2, 2014, 5:38 AM	Apr 5, 2014, 6:11 AM	65	PWD MAINE
BYFHH6	(E) SEWER SUMP- PUMP NOT WORKING AGAIN CAUSING SEWAGE TO OVERFLOW FROM THE FLOOR TANK INTO THE WORKSPACE.BAS EMENT OF H-10, MWR GEAR ISSUE AREA 438-1514	CLOSE	PNSY-H10	Apr 4, 2014, 9:05 AM	Apr 4, 2014, 11:00 AM	Apr 4, 2014, 1:00 PM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
BYFWRF	ORDER AND INSTALL GRINDER PUMP	CLOSE	PNSY-H10	Apr 7, 2014, 10:30 AM	Apr 7, 2014, 10:30 AM	Jun 14, 2014, 2:30 PM	65	PWD MAINE
BYKBPR	Building H10_Pack light is out please relamp	CLOSE	PNSY-H10	Apr 17, 2014, 6:21 AM	Apr 17, 2014, 12:47 PM	Oct 9, 2014, 11:36 AM	65	PWD MAINE
BYSBHY	(P) IN YOUTH CENTER---BOYS ROOM---0-SINK FAUYCET OVERFLWOING SINK AND TOIULET OVERFLOWING IN SAME HEAD	CLOSE	PNSY-H10	Apr 24, 2014, 12:20 PM	Apr 24, 2014, 12:30 PM	Apr 25, 2014, 2:30 PM	65	PWD MAINE
BYSJVP	Building H10_IN YOUTH CENTER_BOYS ROOM0SINK FAUCET OVERFLOWING SINK AND TOILET OVERFLOWING IN SAME HEAD	CLOSE	PNSY-H10	Apr 25, 2014, 7:48 AM	Apr 28, 2014, 6:00 AM	Apr 28, 2014, 8:00 AM	65	PWD MAINE
BZ4ZYF	ANNUAL PM ROUTE CONDENSING UNIT, AIR COOLED	CLOSE	PNSY-H10	May 20, 2014, 11:58 PM	May 27, 2014, 4:22 AM	Aug 25, 2014, 7:53 AM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
BZHGHS	H10: PREPARE ESTIMATE FOR COMPLETE REPAIR OF HVAC SYSTEM	CAN	PNSY-H10	Jun 10, 2014, 8:57 AM			65	PWD MAINE
BZKMYJ	ANNUAL PM ROUTE AIR HANDLING UNIT	CLOSE	PNSY-H10	Jun 18, 2014, 7:30 PM	Jul 10, 2014, 5:52 AM	Aug 10, 2014, 5:23 PM	65	PWD MAINE
BZNLYP	Building h10_Replace tile floor, paint walls and replace a door_ This is a CREDIT CARD job	CLOSE	PNSY-H10	Jun 24, 2014, 10:03 AM	May 1, 2015, 9:36 AM	Jan 29, 2016, 8:28 AM	65	PWD MAINE
BZRKF4	(P) MEN AN KIDS REST RM TOILETS OVERFLOWING WITH STUFF TRYED TO SNAKE WITH NO LUCK	CLOSE	PNSY-H10	Jun 26, 2014, 8:25 AM	Jun 26, 2014, 9:30 AM	Jun 26, 2014, 12:30 PM	65	PWD MAINE
BZRLHP	E, Repair, replace lock and key on building H-10	CLOSE	PNSY-H10	Jun 23, 2014, 3:14 PM	Jul 1, 2014, 6:00 AM	Jul 1, 2014, 2:30 PM	65	PWD MAINE
BZS44D	Install K/O plug in numerous locations.	CAN	PNSY-H10	Jun 27, 2014, 5:27 AM			65	PWD MAINE
BZW43V	Building h-10_Toilet not flushing in child care area	CLOSE	PNSY-H10	Jul 3, 2014, 2:44 PM	Jul 2, 2014, 6:00 AM	Jul 3, 2014, 9:00 AM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
BZWNLW	(E) REPAIR TOILET IN SCHOOL LIASISON OFFICE AREA---NOT FLUSHING PROPERLY--- HAVE CHILDREN IN AREA	CLOSE	PNSY-H10	Jul 7, 2014, 1:49 PM	Jul 10, 2014, 6:00 AM	Jul 11, 2014, 6:30 AM	65	PWD MAINE
BZWNSV	Toilet not flushing in child care area	CAN	PNSY-H10	Jul 7, 2014, 4:53 PM			65	PWD MAINE
C3RMFT	P) 1ST FL FEMALE HEAD UNCLOGG SINK DRAIN	CLOSE	PNSY-H10	Aug 25, 2014, 10:38 AM	Aug 25, 2014, 11:33 AM	Aug 25, 2014, 2:30 PM	65	PWD MAINE
C3YZYC	QUARTERLY PM ROUTE AIR HANDLING UNIT	CLOSE	PNSY-H10	Sep 17, 2014, 1:05 PM	Sep 30, 2014, 12:49 PM	Dec 1, 2014, 12:44 PM	65	PWD MAINE
C4C4BX	ANNUAL PM, FIRE ALARM CONTROL PANEL	CLOSE	PNSY-H10	Sep 27, 2014, 5:38 PM	Sep 30, 2014, 12:49 PM	Oct 16, 2014, 2:30 PM	65	PWD MAINE
C4CP39	BUILDING H10, BUILDING OUTSIDE PERIMETER LIGHTING FIXUTRES INOP.	CLOSE	PNSY-H10	Sep 29, 2014, 12:58 PM	Sep 29, 2014, 1:38 PM	Oct 14, 2014, 12:39 PM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
C4FS6B	(F) REQUEST REPLACEMENT OFBROKEN CEILING TILES ANBD WATER STAINED CEILIBNG TILES IH THE YOU8TH CENT LOCATED INB BLDG H-10	CLOSE	PNSY-H10	Oct 6, 2014, 1:56 PM	Oct 8, 2014, 6:00 AM	Oct 14, 2014, 2:30 PM	65	PWD MAINE
C4FS6G	(f) replace light bulbs in the youth center located in bldg H- 10....minimum of 3 so far	CLOSE	PNSY-H10	Oct 6, 2014, 2:01 PM	Oct 7, 2014, 9:28 AM	Oct 14, 2014, 12:45 PM	65	PWD MAINE
C4JGPL	(e) Bldg H10 - Install plexi-glass vision panels in two (2) of the doors on the north, child youth center end of the building to provide visibility in	CLOSE	PNSY-H10	Oct 15, 2014, 1:37 PM	Oct 23, 2014, 6:00 AM	Oct 29, 2014, 2:30 PM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
C4SGGL	F) REQUEST ELECTRICITY BE SET UP FOR DESK / COMPUTERS IN THE YOUTH CENTER SCHOOL AGE CARE BEHIND THE RECEPTION CLERK DESK	CLOSE	PNSY-H10	Oct 24, 2014, 7:20 AM	Nov 18, 2014, 6:00 AM	Dec 5, 2014, 2:30 PM	65	PWD MAINE
C4TGWD	(e) Bldg H10 - replace main steam valve for building. Valve is leaking.	CLOSE	PNSY-H10	Oct 28, 2014, 3:39 PM	Oct 29, 2014, 6:00 AM	Nov 30, 2014, 2:30 PM	65	PWD MAINE
C4WVPC	PM SEWER LIFT STATION (YEARLY)	CLOSE	PNSY-H10	Nov 5, 2014, 4:01 PM	Nov 17, 2014, 6:00 AM	Nov 20, 2014, 4:00 PM	65	PWD MAINE
C6D9JH	HVAC Materials	CLOSE	PNSY-H10	Dec 1, 2014, 1:46 PM	Jun 15, 2016, 6:54 AM	Jun 15, 2016, 6:54 AM	65	PWD MAINE
C6GJM6	Building H10_Electrical room in the gear rental area is saturated with condensation as steam is leaking out of the steam trench	CLOSE	PNSY-H10	Dec 8, 2014, 2:57 PM	Dec 9, 2014, 6:00 AM	Dec 9, 2014, 3:30 PM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
C6J4YD	(E) my office is in the back of h-10 in the outdoor recreation office!! i have a couple lights in my back room that are blinking !!	CLOSE	PNSY-H10	Dec 12, 2014, 11:33 AM	Dec 15, 2014, 8:08 AM	Jan 5, 2015, 12:55 PM	65	PWD MAINE
C6J6R3	QUARTERLY PM ROUTE AIR HANDLING UNIT	CLOSE	PNSY-H10	Dec 15, 2014, 7:52 AM	Dec 15, 2014, 10:46 AM	Jan 19, 2015, 2:30 PM	65	PWD MAINE
C6VPJF	(F) SCHOOL LIAISON OFFICE - TOILET WILL NOT FLUSH, CHAIN HAS BROKEN AT TOP & BOTTOM	CLOSE	PNSY-H10	Jan 8, 2015, 11:49 AM	Jan 15, 2015, 6:00 AM	Jan 15, 2015, 8:00 AM	65	PWD MAINE
C6VPVP	BLDG: H-10 Fitness Center Side- Steam Leak 6-8" of water	CLOSE	PNSY-H10	Jan 8, 2015, 2:58 PM	Jan 9, 2015, 9:18 AM	Jan 9, 2015, 9:18 AM	65	PWD MAINE
C6VPVR	(p) ck/repair bad steam leakj in 1st deck stairwell on west side of bldg--- have approx. 6" of water from radiator and coming down the steps	CAN	PNSY-H10	Jan 8, 2015, 2:58 PM			65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
C6VTTS	BLDG: H-10 FOLLOW_UP - Fitness Center Side- Steam Leak 6-8" of water	CLOSE	PNSY-H10	Jan 9, 2015, 9:18 AM	Mar 4, 2015, 11:01 AM	Mar 4, 2015, 11:01 AM	65	PWD MAINE
C7GCCT	BUILDING H-10, re pipe condensate drain. Drain is in front of the filter	CLOSE	PNSY-H10	Jan 29, 2015, 12:22 PM	Jan 30, 2015, 8:00 AM	Jan 30, 2015, 1:00 PM	65	PWD MAINE
C7K6XR	E, around back in the basement Outdoor recreation office, outside motor for the sewer and heat, making noise	CLOSE	PNSY-H10	Feb 2, 2015, 1:20 PM	Feb 3, 2015, 6:00 AM	Apr 10, 2015, 2:30 PM	65	PWD MAINE
C7NPTY	BLDG: H-10 Lower level 1st FLR- Install aerators (sorry about spelling) on the 2 sinks in the "Clubhouse" near Hobby Shop	CLOSE	PNSY-H10	Feb 10, 2015, 1:26 PM	Feb 10, 2015, 1:30 PM	Feb 11, 2015, 12:38 PM	65	PWD MAINE
C7YLKS	BLDG: H-10 / Entryway - repair a piece of leaking radiator heating	CLOSE	PNSY-H10	Feb 17, 2015, 12:07 PM	Mar 17, 2015, 1:00 PM	Mar 23, 2015, 3:30 PM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
C7ZVPD	Building h-10_Please remove and replace faucets, piping and shut-off valves for the 2nd deck men's and women's head, clubhouse sinks as well.	CLOSE	PNSY-H10	Feb 19, 2015, 12:18 PM	Feb 20, 2015, 6:00 AM	Apr 14, 2015, 2:30 PM	65	PWD MAINE
C9BTVD	F) NUMEROUS OF CEILING TILES ARE DAMAGED WITH WATER STAINS AND NEEDS TO BE CHANGED.	CAN	PNSY-H10	Mar 2, 2015, 2:04 PM			65	PWD MAINE
C9HBXP	BLDG: H-10 - OUTAGE # 150472 - Shop Outage support for Fire Drill at the Youth Center	CLOSE	PNSY-H10	Mar 12, 2015, 9:51 AM	Mar 20, 2015, 9:00 AM	Mar 20, 2015, 9:30 AM	65	PWD MAINE
C9HD36	BLDG: H-10 - OUTAGE # 150473 - Shop Outage support for Fire Drill at the Youth Center	CLOSE	PNSY-H10	Mar 12, 2015, 10:22 AM	Mar 17, 2015, 9:00 AM	Apr 17, 2015, 9:30 AM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
C9JX7P	Bldg H10 - 1st floor day care area - 2 emergency lights out and need repair	CLOSE	PNSY-H10	Mar 16, 2015, 3:41 PM	Mar 17, 2015, 7:02 AM	Apr 21, 2015, 9:16 AM	65	PWD MAINE
C9LWVZ	QUARTERLY PM ROUTE AIR HANDLING UNIT	CLOSE	PNSY-H10	Mar 19, 2015, 10:38 AM	Apr 1, 2015, 6:19 AM	May 12, 2015, 3:30 PM	65	PWD MAINE
C9Z3ZC	(E) MWR WOODSHOP INDOOR OVERHEAD LIGHTING FIXTURES SEVERAL HEAT VAPOR LIGHT BULBS ARE OUT AND NEED TO BE RELPAED.	CLOSE	PNSY-H10	Mar 27, 2015, 1:40 PM	Mar 27, 2015, 2:21 PM	Apr 21, 2015, 9:18 AM	65	PWD MAINE
CB3YD7	bldg H10 - restroom below Director's office has toilet that is contantly running and causing water to splash over onto floor.	CLOSE	PNSY-H10	Mar 30, 2015, 8:23 AM	Mar 30, 2015, 9:00 AM	Mar 30, 2015, 3:30 PM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
CB64CT	(F) JUST OUTSIDE THE REST.RM. THE OVERHEAD LIGHT COVER NEEDS REPLACED (ITS CRACKED)	CLOSE	PNSY-H10	Mar 31, 2015, 9:44 AM	Apr 1, 2015, 7:31 AM	May 5, 2015, 8:29 AM	65	PWD MAINE
CB9BDX	Secure leaking Black Iron Pipe and clean up spill	CLOSE	PNSY-H10	Apr 2, 2015, 11:49 AM	Apr 2, 2015, 12:00 PM	Apr 2, 2015, 3:30 PM	65	PWD MAINE
CB9BHJ	Building h10_Emergency cleaning for pipe burst.	CLOSE	PNSY-H10	Apr 2, 2015, 12:41 PM	May 20, 2015, 7:40 AM	May 20, 2015, 7:40 AM	65	PWD MAINE
CBCT6T	Building H10_Repaint hallway and entry area after steam leak damaged paint.	CLOSE	PNSY-H10	Apr 6, 2015, 6:37 AM	May 20, 2015, 7:40 AM	May 20, 2015, 7:40 AM	65	PWD MAINE
CBFG6T	OUTAGE# 150594 - BLDG: H-10 - Request Shop Fire Alarm Tech. to support Contractor with Outage.	CLOSE	PNSY-H10	Apr 8, 2015, 11:03 AM	May 7, 2015, 8:00 AM	May 7, 2015, 12:00 PM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
CBYN9X	(E) OUTDOOR recreation office down around back of h-10 have a gfi outlet that keeps tripping, a freeze is plug in to it!!	CAN	PNSY-H10	Apr 21, 2015, 11:23 AM			65	PWD MAINE
CBYNB4	(E) OUTDOOR recreation office down around back of h-10 have a gfi outlet that keeps tripping, a freeze is plug in to it!!	CLOSE	PNSY-H10	Apr 21, 2015, 1:46 PM	Apr 22, 2015, 6:00 AM	Apr 22, 2015, 2:30 PM	65	PWD MAINE
CCRSPP	P, SEPTIC PUMP LEAKING	CLOSE	PNSY-H10	May 6, 2015, 8:43 AM	May 6, 2015, 9:30 AM	May 6, 2015, 1:30 PM	65	PWD MAINE
CCRTMW	Building h-10 club house faucets in basement_Removal of all copper piping in coordination with the lead in priority project	CLOSE	PNSY-H10	May 6, 2015, 11:10 AM	May 20, 2015, 7:17 AM	May 20, 2015, 7:17 AM	65	PWD MAINE
CD6KZX	P)RPR 2 ROLL UP DOORS LOST POWER	CAN	PNSY-H10	May 18, 2015, 11:26 AM			65	PWD MAINE
CD6VML	ANNUAL PM ROUTE CONDENSING UNIT, AIR COOLED	CLOSE	PNSY-H10	May 19, 2015, 1:35 PM	Jun 1, 2015, 7:14 AM	Jul 30, 2015, 3:30 PM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
CDC9KL	P)RPR 2 ROLL UP DOORS LOST POWER_The FMS inspected the area, the sub-panel has not tripped but the main panel couldn't be accessed. Please assess	CLOSE	PNSY-H10	May 20, 2015, 8:49 AM	May 21, 2015, 6:00 AM	May 21, 2015, 2:30 PM	65	PWD MAINE
CDD4WX	Outage 150876 - bldg H10 - need F/A tech to support outage	CLOSE	PNSY-H10	May 22, 2015, 2:00 PM	May 27, 2015, 4:00 PM	May 27, 2015, 4:30 PM	65	PWD MAINE
CDD4X4	Outage 150877 - bldg H10 - need F/A tech to support outage	CLOSE	PNSY-H10	May 22, 2015, 2:09 PM	Jun 19, 2015, 9:00 AM	Jun 19, 2015, 9:30 AM	65	PWD MAINE
CDD4XB	Outage 150878 - bldg H10 - need F/A tech to support outage	CLOSE	PNSY-H10	May 22, 2015, 2:15 PM	Jul 16, 2015, 8:00 AM	Jul 16, 2015, 9:00 AM	65	PWD MAINE
CDFP4P	Follow-up WO to have shop plumbers make the proper repairs on the septic pump once a contractor pumps down the sewer tanks.	CLOSE	PNSY-H10	May 27, 2015, 7:42 AM	Aug 24, 2015, 9:51 AM	Aug 24, 2015, 9:51 AM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
CDF6W	Follow-up WO to hire in a Contractor to pump sewer out from pump in order to allow our shop to perform repairs needed.	CLOSE	PNSY-H10	May 27, 2015, 7:54 AM	May 27, 2015, 9:00 AM	Jun 23, 2015, 2:30 PM	65	PWD MAINE
CDJRXN	(F) 2,REST RM'S,AN ONE ADDITIONAL SINK NO HOT WATER WHICH IS REQUIRED FOE CHILDREN HAND WASHING	CLOSE	PNSY-H10	Jun 9, 2015, 6:30 AM	Jun 9, 2015, 7:00 AM	Jun 9, 2015, 11:00 AM	65	PWD MAINE
CDJSM7	(F) CEILING LIGHT OUT,YOUTH CENTER BACK RM BY "BUS STOP DOOR"	CLOSE	PNSY-H10	Jun 9, 2015, 6:27 AM	Jun 9, 2015, 12:04 PM	Jun 15, 2015, 1:10 PM	65	PWD MAINE
CDLN99	E, 2ND FLR, MEN BATHROOM URINAL LEAKING	CLOSE	PNSY-H10	Jun 15, 2015, 12:25 PM	Jun 16, 2015, 6:00 AM	Jun 27, 2015, 2:30 PM	65	PWD MAINE
CDLNHJ	E, 2ND FLR, (8) FLOURESCEN T LIGHT OUT MAIN HALLWAY	CLOSE	PNSY-H10	Jun 15, 2015, 12:17 PM	Jun 15, 2015, 1:24 PM	Jun 15, 2015, 1:24 PM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
CDLRDR	E, 2ND FLR, (8) FLOURESCEN T LIGHT OUT MAIN HALLWAY	CLOSE	PNSY-H10	Jun 15, 2015, 1:28 PM	Jun 15, 2015, 2:00 PM	Jun 30, 2015, 12:26 PM	65	PWD MAINE
CDLVSK	bldg H-10 - Outdoor Recreation office - repair hole in wall; hole was made during recent electrical repair to GFI wiring on work order CBYNB4	CLOSE	PNSY-H10	Jun 16, 2015, 12:19 PM	Jun 16, 2015, 1:00 PM	Jun 19, 2015, 2:30 PM	65	PWD MAINE
CDN6T3	ANNUAL PM ROUTE AIR HANDLING UNIT	CLOSE	PNSY-H10	Jun 18, 2015, 1:34 PM	Jul 14, 2015, 6:30 AM	Jul 14, 2015, 3:15 PM	65	PWD MAINE
CFMT6K	(F) REPAIR TOILET IN YOUTH CENTER==1ST BATHROOM ON RIGHT AS YOU ENTER CLASSROOM	CLOSE	PNSY-H10	Aug 18, 2015, 2:16 PM	Aug 26, 2015, 6:00 AM	Aug 26, 2015, 3:30 PM	65	PWD MAINE
CFNMFG	H-10 - FIRST FLOOR - CHILD DEVELOPMENT	CLOSE	PNSY-H10	Aug 20, 2015, 12:55 PM	Aug 20, 2015, 2:00 PM	Aug 20, 2015, 4:30 PM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
CFVGTT	OUTAGE # A 150459 - H-10 - SECURE F/A SPRINKLER ZONES AS NEEDED FOR UEM CREW.	CLOSE	PNSY-H10	Aug 31, 2015, 2:09 PM	Sep 2, 2015, 8:00 AM	Sep 2, 2015, 3:30 PM	65	PWD MAINE
CFWRKF	BLDG: H-10 - Repair / Replace Back entrance wood stair treads falling off.	CLOSE	PNSY-H10	Sep 2, 2015, 2:37 PM	Sep 9, 2015, 6:00 AM	Sep 17, 2015, 3:30 PM	65	PWD MAINE
CGHSTR	ANNUAL PM, FIRE ALARM CONTROL PANEL	CLOSE	PNSY-H10	Sep 18, 2015, 9:08 PM	Oct 2, 2015, 7:36 AM	Oct 6, 2016, 1:08 PM	65	PWD MAINE
CGL6CT	Outage # 151371 - BLDG: H-10 - SHOP SUPPORT DURING FIRE DRILL	CLOSE	PNSY-H10	Sep 21, 2015, 6:51 AM	Sep 28, 2015, 2:00 PM	Sep 28, 2015, 3:00 PM	65	PWD MAINE
CGLWPZ	QUARTERLY PM ROUTE AIR HANDLING UNIT	CLOSE	PNSY-H10	Sep 21, 2015, 5:01 PM	Sep 30, 2015, 7:55 AM	Oct 13, 2015, 3:30 PM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
CGPPGX	(P) CK/REPAIR GARAGE DOOR #1- -REPAIR CABLE THAT HAS DISCONNECTED FROM DOOR....DOOR IS IN THE DOWN POSITION AT PRESENT	CLOSE	PNSY-H10	Sep 25, 2015, 11:37 AM	Sep 28, 2015, 7:12 AM	Jan 11, 2016, 8:09 AM	65	PWD MAINE
CJC6FL	(F) THERE ARE SEVERAL CEILING TILES THAT ARE STAINED AN NEED TO BE CHANGED(SEE POC FOR COUNT)	CLOSE	PNSY-H10	Oct 28, 2015, 6:48 AM	Jan 20, 2016, 6:00 AM	Jan 20, 2016, 3:30 PM	65	PWD MAINE
CJMBLX	PM SEWER LIFT STATION (YEARLY)	CLOSE	PNSY-H10	Nov 5, 2015, 7:10 AM	Dec 18, 2015, 6:00 AM	Dec 22, 2015, 4:00 PM	65	PWD MAINE
CJRV6S	BLDG: H-10 - ELECTRICAL UPGRADES IN STORE ROOM	CLOSE	PNSY-H10	Nov 10, 2015, 3:01 PM	Nov 12, 2015, 6:00 AM	Dec 5, 2015, 2:30 PM	65	PWD MAINE
CJSHGB	Building h10_ Install carpet tiles and repair door in new ICO office	CLOSE	PNSY-H10	Nov 11, 2015, 10:17 PM	Jun 14, 2016, 2:16 PM	Jun 14, 2016, 2:16 PM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
CJSNWD	BLDG: H-10 / 2nd FLR - Double Steel Entry Door rubbing on floor and needs to be adjusted.	CLOSE	PNSY-H10	Nov 12, 2015, 9:27 AM	Nov 12, 2015, 10:11 AM	Nov 17, 2015, 12:09 PM	65	PWD MAINE
CJSW9B	Building H10 â€œ Office Renovation & Paint	CLOSE	PNSY-H10	Nov 12, 2015, 10:34 AM	Jun 14, 2016, 2:17 PM	Jun 14, 2016, 2:17 PM	65	PWD MAINE
CJVJRK	BLDG: H-10 / FLR 2 Re-attach exit sign hanging from ceiling	CLOSE	PNSY-H10	Nov 16, 2015, 1:06 PM	Nov 16, 2015, 1:30 PM	Nov 17, 2015, 3:30 PM	65	PWD MAINE
CJWD3J	(E) MY STEAM HEAT UNIT IS LEAKING WATER ALL OVER THE PLACE	CLOSE	PNSY-H10	Nov 17, 2015, 12:29 PM	Nov 17, 2015, 1:00 PM	Nov 17, 2015, 3:30 PM	65	PWD MAINE
CK4PTW	(P) 1ST FL SARP OFFICE CEILING TILES ARE WET NEED TO TROUBLESHOOT AND REPAIR LEAK IN PIPING AND REPLACE WET TILES AFTERWARDS.	CLOSE	PNSY-H10	Nov 19, 2015, 8:42 AM	Jan 26, 2016, 6:00 AM	Jan 26, 2016, 12:30 PM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
CK6R79	Outage 160217 - bldg H10 - request FA tech assist to support monthly fire drill	CLOSE	PNSY-H10	Nov 20, 2015, 10:18 AM	Jan 29, 2016, 9:26 AM	Jan 29, 2016, 9:26 AM	65	PWD MAINE
CK6RD4	Outage 160218 - bldg H10 - request FA tech assist to support monthly fire drill	CLOSE	PNSY-H10	Nov 20, 2015, 11:34 AM	Jan 29, 2016, 9:26 AM	Jan 29, 2016, 9:26 AM	65	PWD MAINE
CK6RD9	Outage 160219 - bldg H10 - request FA tech assist to support monthly fire drill	CLOSE	PNSY-H10	Nov 20, 2015, 11:37 AM	Jan 29, 2016, 9:26 AM	Jan 29, 2016, 9:26 AM	65	PWD MAINE
CKLLX7	(P)BASEMENT HEATING UNIT LEAKING AT THE PUMP SEE POC	CLOSE	PNSY-H10	Dec 8, 2015, 8:55 AM	Dec 14, 2015, 7:30 AM	Dec 14, 2015, 3:30 PM	65	PWD MAINE
CKTBZK	(E) 2ND FL request to have MWR old storage room now new IT office double door re-keyed	CLOSE	PNSY-H10	Dec 15, 2015, 7:46 AM	Jan 4, 2016, 6:00 AM	Jan 4, 2016, 3:30 PM	65	PWD MAINE
CKW4SR	QUARTERLY PM ROUTE AIR HANDLING UNIT	CLOSE	PNSY-H10	Dec 19, 2015, 3:26 PM	Dec 30, 2015, 9:23 AM	Jan 5, 2016, 3:30 PM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
CLSNK3	BLDG: H-10 / Basement - Troubleshoot and repair water leak	CLOSE	PNSY-H10	Jan 13, 2016, 8:39 AM	Jan 12, 2016, 9:00 AM	Jan 22, 2016, 11:30 AM	65	PWD MAINE
CMJVVT	H-10 / Youth Center FLR 1 - Multiple fluorescent lightbulbs out throughout the center. Please Replace	CLOSE	PNSY-H10	Jan 27, 2016, 10:27 AM	Jan 27, 2016, 11:03 AM	Feb 1, 2016, 1:47 PM	65	PWD MAINE
CMRNXY	F) OUR SCHOOL AGE CARE PROGRAM IS LOCATED IN AN OLD OFFICE SPACE WITH LARGE VAULT. SAFETY HAZARD & WE NEED TUMBLER & HANDLE REMOVED SO WE CAN SECURE	CLOSE	PNSY-H10	Feb 1, 2016, 6:48 AM	Feb 2, 2016, 6:00 AM	Feb 2, 2016, 3:30 PM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
CMST7S	F) LOCK ON THE DOOR OF H10 ON ROADSIDE OF BLDG WILL NOT SHUT OR LOCK. THIS IS THE DOOR THAT THE KIDS LOAD & OFF LOAD FROM THE BUS.	CLOSE	PNSY-H10	Feb 2, 2016, 7:58 AM	Feb 2, 2016, 11:30 AM	Feb 2, 2016, 3:30 PM	65	PWD MAINE
CN3L4C	BLDG: H-10/2nd deck_Student Liaison area_Water leak has covered all of area and starting to smell please clean up, see POC and she will direct	CAN	PNSY-H10	Feb 16, 2016, 11:12 AM			65	PWD MAINE
CNC4DN	F) 1SF FLOOR ENTRYWAY ACROSS FROM LC11. REPAIR FROZEN AND BURST HEATER PIPING.	CLOSE	PNSY-H10	Feb 17, 2016, 7:15 AM	Feb 22, 2016, 6:00 AM	Mar 17, 2016, 8:30 AM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
CNDMVR	F) UNCLOGG DRAIN BACK UP SINKS OUTSIDE OF BATHROOM_BOT H SINKS WILL NOT DRAIN PLEASE UNCLOG	CLOSE	PNSY-H10	Feb 18, 2016, 4:24 AM	Feb 22, 2016, 8:30 AM	Feb 24, 2016, 7:00 AM	65	PWD MAINE
CNFPHC	OUTAGE # 160527 - BLDG: H-10 / YOUTH CENTER - SECURE F/A SYSTEM IN SUPPORT OF FIRE DRILL	CLOSE	PNSY-H10	Feb 23, 2016, 1:24 PM	Feb 29, 2016, 3:15 PM	Mar 2, 2016, 12:30 PM	65	PWD MAINE
CNHXBL	ANNUAL PM, ICAP METER UPDATE	CLOSE	PNSY-H10	Mar 1, 2016, 1:14 PM	Mar 24, 2016, 6:14 AM	Mar 24, 2016, 6:14 AM	65	PWD MAINE
CNN3LP	H-10 water temp is 110 degrees and despite adjusting T- stat to a higher temp, it remains at 110 degrees	CLOSE	PNSY-H10	Mar 14, 2016, 9:05 AM	Mar 16, 2016, 6:00 AM	Mar 17, 2016, 3:30 PM	65	PWD MAINE
CNRNTS	QUARTERLY PM ROUTE AIR HANDLING UNIT	CLOSE	PNSY-H10	Mar 19, 2016, 5:12 PM	Apr 1, 2016, 6:00 AM	Apr 21, 2016, 3:30 PM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
CNZDWT	(F) THE LIGHTBULB NEAR THE CLERKS DESK IS OUT AND NEEDS TO BE REPLACED	CLOSE	PNSY-H10	Mar 21, 2016, 10:26 AM	Mar 22, 2016, 7:18 AM	Apr 4, 2016, 7:13 AM	65	PWD MAINE
CPHX6V	H10 floor 1 - repair SARP bathroom door handle which is loose and does not lock	CLOSE	PNSY-H10	Apr 18, 2016, 8:46 AM	Apr 20, 2016, 1:39 PM	May 11, 2016, 7:22 AM	65	PWD MAINE
CPP3MS	(E) 1ST FL SARP OFFICE UNISEX HEAD LIGHTS NEED REPLACED	CLOSE	PNSY-H10	Apr 20, 2016, 9:34 AM	Apr 20, 2016, 1:26 PM	May 9, 2016, 12:31 PM	65	PWD MAINE
CPPS6V	P) IN BASEMENT RPR STEAM LEAKE FORM HOT WTR SYSTEM	CLOSE	PNSY-H10	Apr 21, 2016, 10:08 AM	Apr 21, 2016, 10:30 AM	Apr 21, 2016, 11:30 AM	65	PWD MAINE
CPSKKH	P) SARP OFFICE DOOR WILL NOT LOCK NEEDS RPR	CLOSE	PNSY-H10	Apr 25, 2016, 8:37 AM	Apr 26, 2016, 8:00 AM	May 20, 2016, 7:00 AM	65	PWD MAINE
CPSP9T	P) IN THE BASEMENT RPR HEAT EXHANGER WTR LEAK	CLOSE	PNSY-H10	Apr 26, 2016, 11:53 AM	Apr 26, 2016, 12:30 PM	Apr 26, 2016, 3:30 PM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
CPTC4P	E) in the outdoor recreation office of h-10 in the basement	CLOSE	PNSY-H10	Apr 27, 2016, 3:01 PM	Apr 28, 2016, 11:00 AM	May 13, 2016, 12:00 PM	65	PWD MAINE
CPW7PY	F) 1ST FL RELAMP LIGHTING IN IN THE CHILDREN BATHROOM IN THE HALLWAY BY THE SINK	CLOSE	PNSY-H10	May 3, 2016, 8:43 AM	May 4, 2016, 7:19 AM	May 9, 2016, 12:22 PM	65	PWD MAINE
CPW9D4	Building h10_ Tear out and reinstall carpet that was damaged by water multiple times in the space during fy16.	CLOSE	PNSY-H10	May 3, 2016, 1:00 PM	Oct 24, 2016, 10:37 AM	Oct 24, 2016, 10:37 AM	65	PWD MAINE
CPZFCT	Outage #160892 bldg. H-10 Fire Drill for the youth center	CLOSE	PNSY-H10	May 13, 2016, 10:28 AM	May 18, 2016, 3:45 PM	May 24, 2016, 12:00 PM	65	PWD MAINE
CPZFD6	Outage #160893 bldg. H-10 Fire Drill for the youth center	CLOSE	PNSY-H10	May 13, 2016, 10:32 AM	Jun 1, 2016, 5:00 AM	Jun 3, 2016, 6:00 AM	65	PWD MAINE
CR6FBJ	ANNUAL PM ROUTE CONDENSING UNIT, AIR COOLED	CLOSE	PNSY-H10	May 19, 2016, 11:03 AM	Jun 1, 2016, 6:29 AM	Jun 23, 2016, 9:45 AM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
CRF3ZL	Building h10_Replace damaged drywall and ceiling tiles from last flood	CLOSE	PNSY-H10	May 24, 2016, 6:14 AM	May 24, 2016, 9:00 AM	Jun 17, 2016, 3:30 PM	65	PWD MAINE
CRJMMX	(P) THRU OUT BLDG MICE EVERYWHERE PLEASE SET TRAPS	CLOSE	PNSY-H10	Jun 1, 2016, 9:26 AM	Jun 2, 2016, 7:55 AM	Dec 2, 2016, 3:01 PM	65	PWD MAINE
CRS9YH	ANNUAL PM ROUTE AIR HANDLING UNIT	CLOSE	PNSY-H10	Jun 18, 2016, 8:35 AM	Jul 5, 2016, 11:18 AM	Jul 15, 2016, 7:56 AM	65	PWD MAINE
CS3RKB	(F) CLUBHOUSE, (PART OF YOUTH CENTER) IN REAR OF BUILDING H-10	CLOSE	PNSY-H10	Jun 28, 2016, 12:08 PM	Jun 29, 2016, 8:00 AM	Aug 8, 2016, 3:10 PM	65	PWD MAINE
CS4GL3	H-10 1st floor rest room toilet has broken flush handle	CLOSE	PNSY-H10	Jun 30, 2016, 11:39 AM	Jun 30, 2016, 12:00 PM	Jul 8, 2016, 11:15 AM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
CSCBGK	F) PEST CONTROL - MICE DROPPING ALL OVER SHELVES & EQUIPMENT. YOUTH CENTER - CLUBHOUSE ANNEX COME TO YOUTH CENTER FOR ESCORT TO CLUBHOUSE STORAGE	CLOSE	PNSY-H10	Jul 15, 2016, 6:20 AM	Jul 15, 2016, 1:51 PM	Dec 2, 2016, 3:00 PM	65	PWD MAINE
CSCX9R	F) ON KITCHEN DOOR A VISION PANEL NEEDS TO BE INSTALLED SO WE CAN VIEW THAT AREA YOUTH CENTER CLINIC END OF BLDGE KITCHEN DOOR NEXT TO OFFICE	CLOSE	PNSY-H10	Jul 15, 2016, 6:29 AM	Jul 18, 2016, 9:00 AM	Oct 19, 2016, 8:33 AM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
CSCX9T	F) ELECTRCIAL BOX ABOVE CLUBHOUSE SHUFFLE BOARD TABLE NOT FULLY SECURED TO CEILING YOUTH CENTER CLUBHOUSE ANNEX COME TO YOUTH CENTER FOR ESCORT TO	CLOSE	PNSY-H10	Jul 15, 2016, 6:25 AM	Jul 18, 2016, 9:00 AM	Jul 26, 2016, 7:45 AM	65	PWD MAINE
CSCXB4	F) 2 DOORS YOUTH CENTER CONFERANCE RM, DOOR TO OFFICE STORAGE DOOR BEWTEEN FRONT RM & CONFERANCE RM HAVE KNOB / LOCK SWITCHED	CLOSE	PNSY-H10	Jul 15, 2016, 6:08 AM	Jul 18, 2016, 11:00 AM	Aug 16, 2016, 1:15 PM	65	PWD MAINE
CSNTSC	FU, BUILDING H10 REPAIR/REPLACE AIR DAMPER	CLOSE	PNSY-H10	Jul 28, 2016, 6:49 AM	Jul 28, 2016, 7:00 AM	Aug 8, 2016, 8:06 AM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
CSRTFP	(F) CABINET DOORS HAVE FALLEN OFF (1) BLACK GAME CABINET BY DIRECTORS OFFICE (MAIN ROOM)	CLOSE	PNSY-H10	Aug 3, 2016, 6:02 AM	Aug 3, 2016, 9:00 AM	Sep 21, 2016, 9:04 AM	65	PWD MAINE
CSV7ZB	Outage #161247 bldg H-10 F/A tech needed for monthly fire drill for youth center	CLOSE	PNSY-H10	Aug 9, 2016, 9:18 AM	Aug 17, 2016, 9:00 AM	Aug 17, 2016, 12:00 PM	65	PWD MAINE
CSV7ZJ	Outage #161248 bldg H-10 F/A tech needed for monthly fire drill for youth center	CAN	PNSY-H10	Aug 9, 2016, 9:21 AM			65	PWD MAINE
CSVBB9	bldg H-10 Repair broken drain line	CLOSE	PNSY-H10	Aug 9, 2016, 12:47 PM	Aug 9, 2016, 1:00 PM	Sep 8, 2016, 12:22 PM	65	PWD MAINE
CTGX CZ	ANNUAL PM UNDERGROUND STRUCTURE, H-10 WETWELL, WET WELL	CLOSE	PNSY-H10	Sep 7, 2016, 10:19 AM	Sep 20, 2016, 6:00 AM	Sep 20, 2016, 4:00 PM	65	PWD MAINE
CTJ9GS	Bldg H10 - request duplicates of multiple keys	CLOSE	PNSY-H10	Sep 12, 2016, 10:03 AM	Sep 12, 2016, 10:30 AM	Sep 16, 2016, 8:07 AM	65	PWD MAINE
CTLJ79	QUARTERLY PM ROUTE AIR HANDLING UNIT	CLOSE	PNSY-H10	Sep 17, 2016, 5:24 AM	Oct 3, 2016, 6:00 AM	Oct 12, 2016, 12:35 PM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
CTSDR4	ANNUAL PM, FIRE ALARM CONTROL PANEL	CLOSE	PNSY-H10	Sep 19, 2016, 1:19 AM	Oct 1, 2016, 7:01 AM	Oct 19, 2016, 6:36 AM	65	PWD MAINE
CTVSTZ	F) 2ND FLOOR EMALE HEAD THE TOILET WILL NOT FLUSH DUE TO THE CHAIN ON THE HANDLE IS BROKEN INSIDE THE TANK.	CLOSE	PNSY-H10	Sep 20, 2016, 8:20 AM	Sep 20, 2016, 2:00 PM	Sep 29, 2016, 8:05 AM	65	PWD MAINE
CTWMGL	E) the toilet in the ladies room does not flush - chain broken	CLOSE	PNSY-H10	Sep 23, 2016, 6:20 AM	Sep 28, 2016, 2:15 PM	Oct 3, 2016, 6:55 AM	65	PWD MAINE
CVRWKM	FU, BUILDING H10, 2 BAD H/S UNITS REPAIR/REPLACE.	CLOSE	PNSY-H10	Oct 24, 2016, 6:33 AM	Oct 24, 2016, 7:00 AM	Nov 9, 2016, 10:38 AM	65	PWD MAINE
CVSWGW	P) T STAT BROKEN, NO HEAT IN SARP SPACES 1ST FLR	CLOSE	PNSY-H10	Oct 25, 2016, 8:02 AM	Oct 25, 2016, 8:30 AM	Oct 26, 2016, 7:18 AM	65	PWD MAINE
CVT3GC	There is an open wall area in the foyer of bldg. H-10 that needs to be enclosed.	CLOSE	PNSY-H10	Oct 25, 2016, 12:14 PM	Oct 25, 2016, 1:00 PM	Dec 27, 2016, 10:31 AM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
CVTH9G	F/O T STAT BROKEN, NO HEAT IN SARP SPACES 1ST FLR	CLOSE	PNSY-H10	Oct 26, 2016, 5:36 AM	Oct 26, 2016, 7:00 AM	Nov 9, 2016, 10:47 AM	65	PWD MAINE
CVTWN7	P) NEED LIGHT BULB CHANGED 2ND FLR DIR OFFICE ALSO	CLOSE	PNSY-H10	Oct 25, 2016, 7:52 AM	Oct 27, 2016, 9:00 AM	Nov 14, 2016, 1:34 PM	65	PWD MAINE
CVXVZY	(F) CLOGGED DRAIN 1ST FLOOR BATHROOM	CLOSE	PNSY-H10	Nov 2, 2016, 6:16 AM	Nov 2, 2016, 11:00 AM	Nov 9, 2016, 6:57 AM	65	PWD MAINE
CVYM9Z	PM SEWER LIFT STATION (YEARLY)	CLOSE	PNSY-H10	Nov 5, 2016, 5:10 AM	Feb 27, 2017, 6:00 AM	Feb 27, 2017, 4:00 PM	65	PWD MAINE
CW3K4N	H-10 2ND FLR IT OFFICE OUTLET NOT WORKING	CLOSE	PNSY-H10	Oct 26, 2016, 10:09 AM	Nov 10, 2016, 10:00 AM	Nov 17, 2016, 10:15 AM	65	PWD MAINE
CW6FKM	Outage # 170236/7/8 bldg H10- F/A tech needed to support monthly fire drill for youth center	CLOSE	PNSY-H10	Nov 16, 2016, 1:32 PM	Nov 16, 2016, 2:00 PM	May 4, 2017, 6:48 AM	65	PWD MAINE
CWF7JK	H-10 record janitors closet so workers can properly lock up gear	CLOSE	PNSY-H10	Nov 21, 2016, 10:55 AM	Dec 14, 2016, 10:10 AM	Dec 14, 2016, 10:10 AM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
CWFNJ9	REPLACE SUMP PUMPS IN MANHOLES	MATREC	PNSY-H10	Nov 22, 2016, 5:18 AM			65	PWD MAINE
CWFRH4	ME, MATERIAL, BLDG: H10, NOBLE QUOTE# QPNS002512 ORM: LOW	MATREC	PNSY-H10	Nov 22, 2016, 10:11 AM			65	PWD MAINE
CWHSB7	E) WOODSHOP. NO HEAT IN THE MWR WOODSHOP BLD H-10. BLOWERS ARE BLOWING COLD AIR	CLOSE	PNSY-H10	Nov 23, 2016, 12:33 PM	Nov 29, 2016, 7:00 AM	Dec 29, 2016, 5:15 AM	65	PWD MAINE
CWJD99	BUILDING H10, OPEN TWO SAFES AND PLACE IN DISABLE CONDITION FOR DISPOSAL.	CAN	PNSY-H10	Nov 30, 2016, 8:13 AM			65	PWD MAINE
CWJNR6	Building h10- Intallation of stair tread cover and carpet tiles	MATREC	PNSY-H10	Dec 1, 2016, 10:58 AM			65	PWD MAINE
CWSJPN	QUARTERLY PM ROUTE AIR HANDLING UNIT	CLOSE	PNSY-H10	Dec 19, 2016, 6:07 AM	Jan 3, 2017, 7:33 AM	Jan 5, 2017, 7:13 AM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
CWTP43	P) RADIATOR NOT WORKING. NO HEAT CURRENT TEMP 20F	CLOSE	PNSY-H10	Dec 19, 2016, 10:22 AM	Dec 19, 2016, 10:30 AM	Dec 19, 2016, 11:30 AM	65	PWD MAINE
CWTRBR	F) LIGHT BULBS ARE OUT ABOVE DIRECTORS DESK.	CLOSE	PNSY-H10	Dec 19, 2016, 9:54 AM	Dec 19, 2016, 11:05 AM	Jan 4, 2017, 10:25 AM	65	PWD MAINE
CWV6RS	F/U RADIATOR NOT WORKING. NO HEAT CURRENT TEMP 20F. Trouble shoot and evaulate	CLOSE	PNSY-H10	Dec 19, 2016, 12:11 PM	Dec 19, 2016, 12:30 PM	Dec 27, 2016, 10:26 AM	65	PWD MAINE
CX3RJB	Building H10_Repair of damaged flooring n the counseling office	MATREC	PNSY-H10	Dec 28, 2016, 11:50 AM			65	PWD MAINE
CXBPMW	Bldg H-10 Paint lobby and game room- was hit on audit team walkthrough	MATREC	PNSY-H10	Jan 10, 2017, 5:58 AM			65	PWD MAINE
CXCSYM	bldg H10- Club house mice/rodent problem due to hole in concrete that needs to be patched	CLOSE	PNSY-H10	Jan 12, 2017, 9:11 AM	Jan 12, 2017, 10:30 AM	Feb 6, 2017, 12:57 PM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
CXR44Y	Outage #170552 bldg H10- F/A is needed in support of monthly fire drill for school age program	CLOSE	PNSY-H10	Jan 25, 2017, 9:35 AM	Jan 26, 2017, 4:00 AM	Feb 24, 2017, 7:00 AM	65	PWD MAINE
CXWGDB	(P) SEVERAL HEATERS ARE NOT WORKING BLDG IS 75 DEGREES	CLOSE	PNSY-H10	Feb 6, 2017, 1:32 PM	Feb 8, 2017, 11:30 AM	Apr 17, 2017, 7:01 AM	65	PWD MAINE
CXXDTS	bldg H10- a toilet listed as RR on the first floor of H10 is leaking from the back forming a small puddle.	CLOSE	PNSY-H10	Feb 10, 2017, 1:23 PM	Feb 10, 2017, 2:00 PM	Feb 24, 2017, 6:33 AM	65	PWD MAINE
CY39SH	ANNUAL PM, ICAP METER UPDATE	CLOSE	PNSY-H10	Feb 16, 2017, 8:39 AM	Apr 6, 2017, 4:26 AM	Apr 6, 2017, 4:26 AM	65	PWD MAINE
CYFLYN	Outage #170663 bldg H10- F/a tech needed to support EVAC drill	COMP	PNSY-H10	Feb 28, 2017, 10:44 AM	Feb 27, 2017, 10:00 AM	Feb 28, 2017, 10:06 AM	65	PWD MAINE
CYGXHM	H10 floor 2 MWR area - broken urinal in mens room	CLOSE	PNSY-H10	Mar 2, 2017, 3:47 PM	Mar 2, 2017, 4:00 PM	Mar 16, 2017, 7:45 AM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
CYHNLH	P) NO HEAT IN MEDICAL CLINIC GARAGE /TRANSPORTATION ONLY 26 DEGREES CANT WORK ON CARS ITS TOO COLD WORK STOPPAGE	CLOSE	PNSY-H10	Mar 6, 2017, 10:49 AM	Mar 6, 2017, 11:00 AM	Mar 6, 2017, 2:30 PM	65	PWD MAINE
CYNWXZ	QUARTERLY PM ROUTE AIR HANDLING UNIT	CLOSE	PNSY-H10	Mar 19, 2017, 12:18 PM	Mar 29, 2017, 9:08 AM	Apr 12, 2017, 7:01 AM	65	PWD MAINE
CZ3H6F	Outage #170827 bldg H10- F/A tech is needed in support of ROUTINE MONTHLY FIRE DRILL FOR SCHOOL AGE CARE PROGRAM.	CLOSE	PNSY-H10	Mar 30, 2017, 7:33 AM	Mar 30, 2017, 6:30 AM	Mar 30, 2017, 8:00 AM	65	PWD MAINE
CZ3H6P	Outage #170828 bldg H10- F/A tech is needed in support of ROUTINE MONTHLY FIRE DRILL FOR SCHOOL AGE CARE PROGRAM.	CLOSE	PNSY-H10	Mar 30, 2017, 7:38 AM	Apr 17, 2017, 8:00 AM	Apr 17, 2017, 10:00 AM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
CZ3H94	Outage #170829 bldg H10- F/A tech is needed in support of ROUTINE MONTHLY FIRE DRILL FOR SCHOOL AGE CARE PROGRAM.	COMP	PNSY-H10	Mar 30, 2017, 7:40 AM	May 10, 2017, 6:00 AM	May 22, 2017, 8:19 AM	65	PWD MAINE
CZ3RNX	bldg H10- Multiple lights need to be relamped or ballast replaced	CLOSE	PNSY-H10	Mar 31, 2017, 7:54 AM	Mar 31, 2017, 8:55 AM	Apr 12, 2017, 10:45 AM	65	PWD MAINE
CZFBKP	E) We are having cameras installed and upon removal of ceiling tiles much moisture was revealed by pipes and wires within ceiling. There	CLOSE	PNSY-H10	Apr 12, 2017, 1:13 PM	Apr 18, 2017, 10:00 AM	Apr 21, 2017, 1:20 PM	65	PWD MAINE
CZTFPC	bldg H10- Clubhouse toilet clogged needs to be investigated and repaired	CLOSE	PNSY-H10	May 2, 2017, 1:40 PM	May 2, 2017, 2:00 PM	May 15, 2017, 7:03 AM	65	PWD MAINE
CZZVC6	E) have a lot of little bulbs out in the offices, basement Outdoor recreation	COMP	PNSY-H10	May 10, 2017, 3:31 PM	May 18, 2017, 10:48 AM	May 23, 2017, 7:19 AM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
D33YRW	ANNUAL PM ROUTE CONDENSING UNIT, AIR COOLED	COMP	PNSY-H10	May 19, 2017, 8:48 AM	May 31, 2017, 12:09 PM	Aug 29, 2017, 1:32 PM	65	PWD MAINE
D3M9JB	Outage #171134 bldg H10- F/A tech is needed in support of welding activities in basement	CAN	PNSY-H10	Jun 13, 2017, 8:57 AM			65	PWD MAINE
D3PVL7	ANNUAL PM ROUTE AIR HANDLING UNIT	COMP	PNSY-H10	Jun 18, 2017, 2:14 PM	Jun 27, 2017, 12:26 PM	Jul 11, 2017, 8:40 AM	65	PWD MAINE
D3XWNZ	bldg H10- 2 exterior windows that are on interior need to be framed in this is safety issue	COMP	PNSY-H10	Jun 22, 2017, 10:55 AM	Jun 22, 2017, 11:00 AM	Aug 16, 2017, 10:47 AM	65	PWD MAINE
D3ZSKW	(P) FRONT ENTRANCE DOOR LOCK BROKEN UNABLE TO SECURE BUILDING	COMP	PNSY-H10	Jun 27, 2017, 9:50 AM	Jun 27, 2017, 10:00 AM	Jun 27, 2017, 2:00 PM	65	PWD MAINE
D3ZTH7	E) Replace fluorescent bulbs in the building H-10 Clinic Garage	COMP	PNSY-H10	Jun 27, 2017, 10:14 AM	Jun 27, 2017, 2:44 PM	Jun 30, 2017, 10:57 AM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
D3ZTRP	Outage 171194 - PNSY-H10 - request FA tech assist to support outage for routine monthly fire drill	COMP	PNSY-H10	Jun 27, 2017, 2:10 PM	Jun 29, 2017, 7:00 AM	Jun 30, 2017, 8:34 AM	65	PWD MAINE
D3ZTS4	Outage 171195 - PNSY-H10 youth center - request FA tech assist to support outage for routine monthly fire drill	COMP	PNSY-H10	Jun 27, 2017, 2:17 PM	Jun 27, 2017, 2:30 PM	Jul 19, 2017, 3:15 PM	65	PWD MAINE
D3ZV4K	Outage 171196 - PNSY-H10 youth center - request FA tech assist to support outage for routine monthly fire drill	COMP	PNSY-H10	Jun 27, 2017, 2:54 PM	Jun 28, 2017, 12:18 PM	Aug 8, 2017, 8:45 AM	65	PWD MAINE
D437WK	(P) LIGHTS IN GARAGE OUT	COMP	PNSY-H10	Jun 27, 2017, 9:47 AM	Jun 28, 2017, 2:23 PM	Jul 12, 2017, 3:08 PM	65	PWD MAINE
D43GVH	H10 Clubhouse toilet severely clogged and needs repair	COMP	PNSY-H10	Jun 29, 2017, 8:53 AM	Jun 29, 2017, 10:00 AM	Jul 5, 2017, 8:06 AM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
D477JH	Outage #171183 bldg H10- F/A tech is needed in support of shutting down electrical panel AC2 to add new boiler	COMP	PNSY-H10	Jul 6, 2017, 7:20 AM	Jul 6, 2017, 7:30 AM	Jul 6, 2017, 11:15 AM	65	PWD MAINE
D4PK3T	E) Sink located in the first floor SARP offices in building H-10 has become dislodged from the wall.	COMP	PNSY-H10	Jul 24, 2017, 10:28 AM	Jul 25, 2017, 11:00 AM	Oct 10, 2017, 1:04 PM	65	PWD MAINE
D4RDVY	Outage 171285 - building H10 - request FA tech assistance to support outage	COMP	PNSY-H10	Jul 26, 2017, 7:46 AM	Jul 26, 2017, 8:00 AM	Jul 26, 2017, 3:15 PM	65	PWD MAINE
D6LF6G	ANNUAL PM UNDERGROUND STRUCTURE, H10 WETWELL, WET WELL	COMP	PNSY-H10	Aug 28, 2017, 2:18 PM	Nov 17, 2017, 6:00 AM	Nov 17, 2017, 4:00 PM	65	PWD MAINE
D6SYJK	BUILDING H10, LOWER LEVEL IN BACK REPAIR/REPLACE TOLIET FOR KIDS CLUB HOUSE AREA IN BLDG.	COMP	PNSY-H10	Sep 5, 2017, 11:10 AM	Sep 5, 2017, 11:30 AM	Sep 13, 2017, 9:28 AM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
D6ZMDF	QUARTERLY PM, AIR HANDLING UNIT	COMP	PNSY-H10	Sep 18, 2017, 3:51 PM	Sep 28, 2017, 7:25 AM	Oct 25, 2017, 6:22 AM	65	PWD MAINE
D7BP66	ANNUAL PM, FIRE ALARM CONTROL PANEL	COMP	PNSY-H10	Sep 19, 2017, 7:47 PM	Sep 28, 2017, 7:12 AM	Oct 24, 2017, 11:45 PM	65	PWD MAINE
D7BXSS	(F) THE 2ND DOOR ENTRANCE INTO THE CLUB HOUSE BUILD THE DOOR IN BETWEEN THE OUTSIDE DOOR AND THE CLASS RM'S IS JAMMED (THE DOOR LATCHS)	COMP	PNSY-H10	Sep 19, 2017, 12:45 PM	Sep 20, 2017, 8:31 AM	Oct 5, 2017, 1:50 PM	65	PWD MAINE
D7DFFN	(F) FRONT RM OF BUILD H-10 IN THE SCHOOL LIASIN'S AREA TOILET HANDLE BROKE OFF9NO LONGER FLUSHES)	COMP	PNSY-H10	Sep 19, 2017, 12:41 PM	Sep 22, 2017, 12:00 PM	Sep 28, 2017, 12:53 PM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
D7M4LZ	(F) LIGHT BULBS ARE OUT IN THE CHILDRENS PLAY AREA, SEE LIST BELOW	COMP	PNSY-H10	Oct 2, 2017, 10:56 AM	Oct 3, 2017, 7:56 AM	Oct 17, 2017, 12:04 PM	65	PWD MAINE
D7SC44	E) Replace light bulbs in SARP bathroom located in SARP office on 1st floor of bldg. H-10. Ms. Emily Daigle at 207-438-6670 is the Administrative	COMP	PNSY-H10	Oct 10, 2017, 9:37 AM	Oct 11, 2017, 8:04 AM	Oct 17, 2017, 3:00 PM	65	PWD MAINE
D7SFWY	(BL-2) sink in bathroom leaks, water is on the floor	COMP	PNSY-H10	Aug 17, 2017, 1:44 PM	Oct 11, 2017, 11:00 AM	Oct 18, 2017, 7:51 AM	65	PWD MAINE
D7TVDB	bldg H10- Hot water control valve needs to be replaced or repaired	COMP	PNSY-H10	Oct 17, 2017, 1:04 PM	Oct 17, 2017, 1:30 PM	Nov 15, 2017, 8:54 AM	65	PWD MAINE
D7TVKZ	(F) ADMIN OFFICE UP STAIRS SINK IS CLOGGED AND SOMETHING IN THE TRAP	COMP	PNSY-H10	Oct 12, 2017, 2:49 PM	Oct 17, 2017, 2:00 PM	Nov 7, 2017, 7:32 AM	65	PWD MAINE
D9DZZ7	PM SEWER LIFT STATION (YEARLY)	MISSEDPM	PNSY-H10	Nov 5, 2017, 4:35 AM	Nov 13, 2017, 9:55 AM	Nov 23, 2017, 3:00 AM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
D9FYKP	E) Several emergency lights did not work.	COMP	PNSY-H10	Nov 1, 2017, 8:11 AM	Nov 7, 2017, 8:04 AM	Nov 13, 2017, 2:04 PM	65	PWD MAINE
D9LJ99	SINK IN CIRCUS ROOM IS DETATCHING FROM THE WALL,STARTING TO LEAK	COMP	PNSY-H10	Oct 11, 2017, 2:54 PM	Nov 17, 2017, 9:30 AM	Nov 30, 2017, 2:12 PM	65	PWD MAINE
D9LJDX	bldg H-10 2nd floor Mens urinal is leaking	COMP	PNSY-H10	Nov 17, 2017, 9:15 AM	Nov 17, 2017, 9:30 AM	Dec 4, 2017, 12:45 PM	65	PWD MAINE
D9XTTN	(P) UTILITY CLOSET HAS A PIPE THAT IS LEAKING	COMP	PNSY-H10	Nov 22, 2017, 1:20 PM	Nov 28, 2017, 11:00 AM	Dec 11, 2017, 11:49 AM	65	PWD MAINE
DB344V	E) Several locations within building H-10 are having issues with the heating system.	APPR	PNSY-H10	Nov 29, 2017, 2:14 PM			65	PWD MAINE
DB7M4J	E) repair electrical outlet in the clubhouse room in Bldg. H-10. Adult child caregiver received a small shock when plugging into the outlet. The outl	COMP	PNSY-H10	Dec 5, 2017, 11:56 AM	Dec 6, 2017, 10:00 AM	Dec 8, 2017, 10:00 AM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
DBCJJB	(P) WATER LEAKING FROM A (WHITE PIPE) IN THE OVERHEAD INTO AN ELECT BOX SEE POC FOR DETAILS AND MAKE ALL REPAIRS AS NEEDED	COMP	PNSY-H10	Dec 14, 2017, 8:03 AM	Dec 14, 2017, 8:30 AM	Dec 14, 2017, 12:00 PM	65	PWD MAINE
DBDBDP	E) Light switch next to the back door in the Youth Center (bldg. H-10) is having electrical issues and has been temporarily taped "off" to prevent	COMP	PNSY-H10	Dec 13, 2017, 1:54 PM	Dec 15, 2017, 10:00 AM	Dec 26, 2017, 8:54 AM	65	PWD MAINE
DBGHKC	F/U to DBCJJB WATER LEAKING FROM A (WHITE PIPE) IN THE OVERHEAD INTO AN ELECT BOX SEE POC FOR DETAILS AND MAKE ALL REPAIRS AS NEEDED	MATREC	PNSY-H10	Dec 19, 2017, 8:06 AM			65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
DBHGHX	QUARTERLY PM, AIR HANDLING UNIT	COMP	PNSY-H10	Dec 19, 2017, 2:50 PM	Dec 28, 2017, 1:33 PM	Jan 25, 2018, 8:53 AM	65	PWD MAINE
DBKHHW	(E) Building H-10 down stairs by the cages in the club house. The door facing the playground has a large gap between the door and the frame of the	COMP	PNSY-H10	Dec 19, 2017, 10:57 AM	Dec 20, 2017, 7:01 AM	Jan 2, 2018, 7:30 AM	65	PWD MAINE
DBVKXZ	(E) Building H-10 SARP Offices on the first floor. Several lights are out and need replacements	COMP	PNSY-H10	Dec 27, 2017, 10:52 AM	Dec 27, 2017, 2:54 PM	Jan 2, 2018, 2:19 PM	65	PWD MAINE
DBVL6J	(E) Building H-10 SARP Offices on the first floor. Bathroom sink is partially off the wall and needs to be secured to the wall.	COMP	PNSY-H10	Dec 27, 2017, 10:55 AM	Dec 27, 2017, 1:30 PM	Jan 19, 2018, 8:10 AM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
DBYVCW	PNSY-H10 - children's club house area - overhead heat pipe on east wall is leaking onto carpet where children are playing	COMP	PNSY-H10	Jan 2, 2018, 10:36 AM	Jan 2, 2018, 11:00 AM	Jan 9, 2018, 10:00 AM	65	PWD MAINE
DCJBGT	F) LIGHT OUT IN GAME ROOM AT YOUTH CENTER.	COMP	PNSY-H10	Jan 19, 2018, 12:55 PM	Jan 23, 2018, 9:38 AM	Feb 2, 2018, 7:15 AM	65	PWD MAINE
DCJBGY	F) FRONT ENTRY WAY LIGHTBULB INOP, 1ST FL, HALLWAY	COMP	PNSY-H10	Jan 19, 2018, 12:54 PM	Jan 23, 2018, 9:46 AM	Jan 29, 2018, 10:24 AM	65	PWD MAINE
DCPBGH	FU BUILDING H10, COMPRESSOR CONTACTOR HAS BURNT CONTACTS, REPAIR/REPLACE.	APPR	PNSY-H10	Sep 5, 2017, 5:54 AM			65	PWD MAINE
DD3P4V	E) 3 FLORESCENT LIGHTS FIXTURES ARE OUT	COMP	PNSY-H10	Feb 16, 2018, 3:51 PM	Feb 20, 2018, 10:27 AM	Mar 1, 2018, 2:37 PM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
DD77CH	(F) LIGHTS OUT OVER TABLE IN OFFICE, OVER COUCHES IN BACK CORNER	COMP	PNSY-H10	Feb 15, 2018, 5:50 AM	Feb 21, 2018, 9:09 AM	Mar 1, 2018, 2:37 PM	65	PWD MAINE
DDCTX6	FU BUILDING H-10, DAMPER ACTUATOR INOP.	APPR	PNSY-H10	Nov 1, 2017, 7:25 PM			65	PWD MAINE
DDF7P4	P) SEVERE WATER LEAK COMING FROM ROOF INTO THE YOUTH CNETERS TRAIING ROOM.	COMP	PNSY-H10	Mar 2, 2018, 11:03 AM	Mar 2, 2018, 11:30 AM	Mar 2, 2018, 2:30 PM	65	PWD MAINE
DDG3R7	FU to work order DDF7P4 -- Replace ceiling tiles due to roof leak INTO THE YOUTH CENTERS TRAINING ROOM.	COMP	PNSY-H10	Mar 5, 2018, 3:30 PM	Mar 5, 2018, 5:00 PM	Mar 14, 2018, 9:35 AM	65	PWD MAINE
DDGRGX	(f) 1st bathroom boys urinal does not flush properly backing up	COMP	PNSY-H10	Feb 15, 2018, 5:47 AM	Mar 6, 2018, 9:00 AM	Mar 12, 2018, 9:49 AM	65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
DDH4ZW	E) Interior entrance door to the Youth Center is missing the slide bolt on the right hand side to keep the door secure when locked. Presently anyone c	COMP	PNSY-H10	Mar 7, 2018, 10:42 AM	Mar 7, 2018, 3:00 PM	Mar 12, 2018, 8:51 AM	65	PWD MAINE
DDHT6H	FU to DDH4ZW - repair slide bolt on Interior entrance door to the Youth Center	COMP	PNSY-H10	Mar 9, 2018, 7:25 AM	Mar 9, 2018, 8:00 AM	Apr 3, 2018, 7:21 AM	65	PWD MAINE
DDJGGD	F) NO HEAT IN BUILDING	COMP	PNSY-H10	Mar 12, 2018, 7:41 AM	Mar 12, 2018, 8:00 AM	Mar 12, 2018, 12:00 PM	65	PWD MAINE
DDJGGG	E) no heat !! the furnace has a warning on it	COMP	PNSY-H10	Mar 9, 2018, 2:52 PM	Mar 12, 2018, 8:00 AM	Mar 13, 2018, 8:47 AM	65	PWD MAINE
DDP4NH	QUARTERLY PM, AIR HANDLING UNIT	COMP	PNSY-H10	Mar 19, 2018, 12:30 PM	Mar 29, 2018, 1:55 PM	Apr 13, 2018, 10:02 AM	65	PWD MAINE
DDTGLP	E)DSN 684-1583Building H-10 SARP Bathroom 1st Floor - Toilets will not flush	APPR	PNSY-H10	Mar 16, 2018, 12:33 PM			65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
DDTGW7	bldg H-10 Medical Clinic Transportation Bay 1st floor - 2 heating zones are not working.	APPR	PNSY-H10	Mar 20, 2018, 8:12 AM			65	PWD MAINE
DDXT7C	bldg H10 - Game room window 1st floor youth center	COMP	PNSY-H10	Mar 21, 2018, 11:47 AM	Mar 21, 2018, 12:36 PM	Apr 13, 2018, 9:46 AM	65	PWD MAINE
DDXT7R	E)One Sodium Vapor light out over the table saw, two fluorescent fixtures that are not working. One in the entrance hall and one by the back door. H	COMP	PNSY-H10	Mar 21, 2018, 8:55 AM	Mar 21, 2018, 12:20 PM	Apr 2, 2018, 12:44 PM	65	PWD MAINE
DF4WZF	F) LIGHT FIXTURE HANGING FROM CEILING INSIDE AND OUTSIDE THE OFFICE	COMP	PNSY-H10	Mar 29, 2018, 11:32 AM	Mar 30, 2018, 1:00 PM	Apr 13, 2018, 6:45 AM	65	PWD MAINE
DF99C4	AIR COMPRESSOR LOCATED IN UTILITY ROOM ON FIRST FLOOR WON'T STOP RUNNING.	APPR	PNSY-H10	Apr 4, 2018, 1:01 PM			65	PWD MAINE

PNSY-H10 Work Orders

WO#	Description	Status	Location	Reported Date	Actual Start	Actual Finish	MDI	PWD
DFWFJV	THE CRANK-OUT WINDOWS (2) IN THE MENS ROOM DO NOT OPEN OR CLOSE DUE TO A BROKEN CRANK MECHANISM ON EACH	ASSIGNED	PNSY-H10	Apr 23, 2018, 12:56 PM	May 2, 2018, 7:48 AM		65	PWD MAINE
DG7MB3	bldg H10- Entry door lock is broken. Vertical latch has become disengaged.	APPR	PNSY-H10	May 10, 2018, 10:57 AM			65	PWD MAINE
DG7WWJ	E) Broken toilet seat in Youth Center.	APPR	PNSY-H10	May 8, 2018, 9:42 AM			65	PWD MAINE
DGCW6V	Water dripping through ceiling into our conference room. Walls are damp, and they are warm (heat pipes?).	APPR	PNSY-H10	May 15, 2018, 10:27 AM			65	PWD MAINE
DGCWWY	PNSY-H10 exterior lights 45, 891, 011 not working; repair/replace	ASSIGNED	PNSY-H10	May 16, 2018, 2:15 PM	May 17, 2018, 10:13 AM		65	PWD MAINE